


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	11/29/2012	1715		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
Containment Branch Recovery Team 4	Name:	Dan Capone START/US EPA	From:	11/29/2012 0700
	Position:	Operations Section Chief	To:	11/29/2012 1630
7. Personnel Roster Assigned				
<u>Name</u>	ICS Position		DUTY CELL	
Dan Capone	Operations Section Chief			
Rex Johnson	Containment Branch Director			
Sean Kane	Field Team Lead/CBR-4			
8. Activity Log				
Activity Area	Morrow Lake (MP 37.00, MP 37.25, MP 37.50)		LAT	LAT
			Various	Various
			(DD.MMMM)	(DD.MMMM)
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA			
	DENSITY OF OIL /SHEEN			
Total Collection Points				
Total Boom Deployed				
Activity	<u>Weston/START CBR 4 Team Activity:</u> Oversight of Enbridge representatives (SWAT, SET, and T&T Salvage) extracting anchor poles (25’Ft, 20’Ft, and 15’Ft long, in 5 foot sections) that were associated with former boom locations; A, B, C-1, D and F-2. A total of sixteen anchor poles were extracted and transferred to the E-4 boat launch where they were staged on poly-vinyl and disassembled into smaller pieces. Enbridge health and safety officer and two sweeper boats were in vicinity during all removal operations.			
Health and Safety Issues	None			
Comments	Sheen and oil globules were identified during anchor extraction activities within the shallow areas of the delta during removal at the former A and B hard-boom locations (MP 37.00 LDB & 37.25 LDB). START Kane assisted in manual labor transferring poles from pontoon boat to jet-boat then to the E-4 boat launch and			

did not identify staining on extracted poles.

Detailed field notes are in CBR-4 Logbook.